

17 April 2024

Byron Shire Council
PO Box 219
MULLUMBIMBY NSW 2482

Dear Sir / Madam

Re: 2 Shelley Drive, Byron Bay – Inspection Certificate

We have inspected the completed concrete retaining wall behind 2B Shelley Drive. Details of the wall are shown on our drawing 231101 S1 revision A.

I certify that the wall is generally in accordance with the design drawings and is structurally adequate in accordance with the relevant codes of Standards Australia and general engineering practices and principles.

This certificate is not to be construed as relieving others of their responsibilities.

If you have any questions, please contact the undersigned.

Yours faithfully



Peter Lucena
Peter Lucena
MIEAust CPEng NER RPEQ VBA
NSW Professional Engineer PRE0001648

Lucena Engineers Pty Ltd